

**LANDING GEAR
&
HYDRAULIC COMPONENT
REPAIRS
FOR
WESTWIND**



Toll Free in USA: 1-877-309-4100

Phone: (936) 494-1717

Fax: (936) 494-1729

WWW.HIGHERPLANES.COM


**ALL MAINTENANCE MANUAL
REPAIRS
PLUS
THE FOLLOWING ↓**



253505-501 / 253505-502 MAIN LANDING GEAR UPPER BODY

OVERHAUL CONSISTS OF:

- NDT
- Restoring diameters as necessary
- Replacing bushings as necessary
- Paint
- Issue FAA form 8130-3 for the overhaul of the assembly



Options OVERHAUL

REPAIR ATTACHMENT LUG
REPAIR DIA A
REPAIR DIA B
REPAIR DIA C
REPAIR DIA D

Options REPAIR DIA E1 REPAIR DIA E2 REPAIR DIA F1 REPAIR DIA F2




INSPECTION FEES APPLY

253511-1 / 253512-1 SCISSOR, LOWER LH & UPPER RH SCISSOR, UPPER LH & LOWER RH

OVERHAUL CONSISTS OF:

- Clean and inspect
- Replace bushings as necessary
- Paint
- Issue FAA form 8130-3 for the overhaul of the assembly



Options

OVERHAUL



INSPECTION FEES APPLY



713096 Series / 4713096 Series NOSE GEAR STEERING CYLINDER

OVERHAUL CONSISTS OF:

- **Restoring main bore and shaft exit lands of housing to new dimensions, if necessary**
- **Restoring end plug shaft exit land, if necessary**
- **Restoring piston / shaft assembly to new dimensions if necessary**
- **Installing all new seals**
- **Testing to more stringent requirements than the aircraft maintenance manual**
- **Issue FAA form 8130-3 for the overhaul of the assembly**



Options

**OVERHAUL
EXCHANGE
CORE CHARGE**




INSPECTION FEES APPLY

713047A G831-4-5 HYDRAULIC FUSE

OVERHAUL CONSISTS OF:

- **Clean and inspect**
- **Replace defective parts**
- **Reseal**
- **Test**
- **Issue FAA form 8130-3 for the overhaul of the assembly**



OPTIONS
OVERHAUL




INSPECTION FEES APPLY

713001-501 / 5713001 / 5713001-501 5713001-501 / 117W50 / 117W50-1 / 4713074 POWER BRAKE VALVE ASSEMBLY

OVERHAUL CONSISTS OF:

- **Inspect and repair housing and components**
- **Restore bores as necessary**
- **Repair and / or replace components as necessary**
- **Assembling with new seals and test to more stringent requirements than OEM**
- **Issue FAA form 8130-3 for the overhaul of the assembly**



OPTIONS **OVERHAUL**



INSPECTION FEES APPLY

713011 / 713011-501 THERMAL RELIEF VALVE

OVERHAUL CONSISTS OF:

- Inspect and repair housing as necessary
- Repair or replacing components as necessary
- Assemble with new seals
- Test
- Issue FAA form 8130-3 for the overhaul of the assembly



OPTIONS OVERHAUL


INSPECTION FEES APPLY



5713061-503 / 713061-505 / 4713028
4713028-501
MLG ACTUATOR

OVERHAUL CONSISTS OF:

- **Inspect and repair or replace components as necessary**
- **Restoring piston / shaft assembly to new dimensions if necessary**
- **Remove and treat corrosion**
- **Installing all new seals**
- **Testing to more stringent requirements than the aircraft maintenance manual**
- **Issue FAA form 8130-3 for the overhaul of the assembly**




OPTIONS
OVERHAUL

INSPECTION FEES APPLY



ES12854-1 / ES12854-501 OUTER STRUT



Options


REPAIR DIA C

REPAIR DIA D

INSPECTION FEES APPLY



ES12858-501 LANDING GEAR INNER BODY



Options OVERHAUL

- REPAIR DIA I
- REPAIR DIA E & SFC B
- REPAIR DIA K
- REPAIR DIA L
- REPAIR DIA A & DIA C & O'Ring Groove


INSPECTION FEES APPLY



F10A5SCH203-1 F10A5SCH203-3 1211164-001 THRUST REVERSER ACTUATOR

OVERHAUL CONSISTS OF:

- **Inspect and repair or replace components as necessary**
- **Modify from -1 to -3 configuration, if necessary**
- **Assemble with new seals**
- **Test**
- **Issue FAA form 8130-3 for the overhaul of the assembly**



OPTIONS OVERHAUL


INSPECTION FEES APPLY



EA1801-2 STEERING VALVE ASSEMBLY

OVERHAUL CONSISTS OF:

- Inspect and repair or replace components as necessary
- Assemble with new seals
- Test
- Issue FAA form 8130-3 for the overhaul of the assembly



OPTIONS OVERHAUL

INSPECTION FEES APPLY



ES12908-503 / -504 910.003.53 / .54 FORK/ROD & AXLE ASSY



OVERHAUL CONSISTS OF:

- Inspect and repair or replace components as necessary
- Assemble & Paint
- Issue FAA form 8130-3 for the overhaul of the assembly

OPTIONS OVERHAUL

REPLACE AXLE
REPLACE ROD

INSPECTION FEES APPLY

**CALL FOR A COMPLETE LIST OF
WESTWIND CAPABILITIES**

PH: (936) 494-1717

TOLL FREE: (877) 309-4100